

## United States Patent and Trademark Office

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
10/758,209	01/14/2004	Samer Kabbani	047589-0167	4869
FOLEY AND	7590 04/25/2007 LARDNER LLP	EXAMINER		
SUITE 500 3000 K STREET NW WASHINGTON, DC 20007			KARLSEN, ERNEST F	
			ART UNIT	PAPER NUMBER
			2829	
		,		
SHORTENED STATUTOR	RY PERIOD OF RESPONSE	MAIL DATE	DELIVERY MODE	
3 MONTHS		04/25/2007	PAPER	

## Please find below and/or attached an Office communication concerning this application or proceeding.

If NO period for reply is specified above, the maximum statutory period will apply and will expire 6 MONTHS from the mailing date of this communication.

Office Action Summary		Application No.	Applicant(s)	
		10/758,209	KABBANI ET AL.	
		Examiner	Art Unit	
		Ernest F. Karlsen	2829	
The MAILING Period for Reply	G DATE of this communication ap	pears on the cover sheet w	ith the correspondence address	
WHICHEVER IS LC - Extensions of time may I after SIX (6) MONTHS fr - If NO period for reply is s - Failure to reply within the Any reply received by the	DNGER, FROM THE MAILING Does available under the provisions of 37 CFR 1.5 om the mailing date of this communication.	DATE OF THIS COMMUNI 136(a). In no event, however, may a will apply and will expire SIX (6) MOI e, cause the application to become A	reply be timely filed  NTHS from the mailing date of this communication.  BANDONED (35 U.S.C. § 133).	
Status				
2a) ☐ This action is 3) ☐ Since this ap	, <del></del>	s action is non-final. ance except for formal mat	ters, prosecution as to the merits is	
Disposition of Claims				
4a) Of the about 5) ☐ Claim(s) 6) ☑ Claim(s) 6-9, 7) ☐ Claim(s)	and 11-30 is/are pending in the above claim(s) 1-5 and 12-26 is/are is/are allowed. 11 and 27-30 is/are rejected. is/are objected to. are subject to restriction and/o	withdrawn from considera	ation.	
Application Papers				
10) The drawing(s Applicant may Replacement of	• , ,	cepted or b) objected to drawing(s) be held in abeya ction is required if the drawing		
Priority under 35 U.S.	C. § 119			
a) All b) S  1. Certifie  2. Certifie  3. Copies  applica	nent is made of a claim for foreign come * c) None of: ad copies of the priority document of the copies of the priority document of the certified copies of the priority document of the copies of the priority document of the copies of the priority document of the certified copies of the certified co	ts have been received. ts have been received in A prity documents have beer nu (PCT Rule 17.2(a)).	Application No n received in this National Stage	
	a's Patent Drawing Review (PTO-948) e Statement(s) (PTO/SB/08)	Paper No	Summary (PTO-413) (s)/Mail Date Informal Patent Application	

Art Unit: 2829

Claims 1-5 and 12-26 are withdrawn from further consideration pursuant to 37 CFR 1.142(b), as being drawn to a nonelected inventions and/or species, there being no allowable generic or linking claim. Applicants timely traversed the restriction (election) requirement in the reply filed on April 18, 2005.

Claims 6-9, 11 and. 27-30 are rejected under 35 U.S.C. 112, first paragraph, as failing to comply with the enablement requirement. The claim(s) contains subject matter which was not described in the specification in such a way as to enable one skilled in the art to which it pertains, or with which it is most nearly connected, to make and/or use the invention. The structure of the apparatus of Figures 3-7 is not clear. The use of the term monolithic is not clear. Is the whole device of Figure 4 supposed to be monolithic or is it just the part labeled 104? Are elements 108 part of the monolithic structure? Part 158 of Figure 3 does not seem to be part of element 104 in Figure 3. Is the part of part 104 on which part 158 is located a surface that is part of part 104? As shown in Figure 3, part 158 seems to extend above the top surface of part 104 where part 106 would presumably attach. It is not clear how a seal would be formed between parts 106 and 104. Figure '3 is supposed to be an exploded view. It appears that part 106 might be exploded and flipped 180 degrees. The bracket with no number in the middle of part 106 appears to be on the wrong side of part 106. It appears that part 106 would be separated from part 104 by part 158 and the bracket with no number on part 106 would just make matters worse. The structure of part 158 to provide the desired function is not understood. If part 158 is on a solid surface of part 104 how does the fluid traverse path Application/Control Number: 10/758,209 Page 3

Art Unit: 2829

124 of Figure 5? The operation and structure of the claimed heat sink is not understood.

Applicants have argued in their response of July 31, 2006 and January 16, 2007 that one of skill in the art could understand the structure of Figures 3-7. Such is not found persuasive and the rejection is repeated.

Any inquiry concerning this communication should be directed to Ernest F. Karlsen at telephone number 571-272-1961.

Ernest F. Karlsen

April 23, 2007

ERNEST KARLSEN PRIMARY EXAMINER